

<b>Water Quality Samples- Lead Testing Results</b>				
<i>Taps with a .0200 lead sample is considered elevated by the EPA and should have action taken to resolve</i>				
		<b>ND= Not detectable</b>		
<b>Building</b>	<b>Location</b>	<b>Result</b>	<b>Date</b>	<b>Corrective Action</b>
Santiam Elementary	Office/staff faucet			
	Rm. 1 fountain	0.0035	07/29/2016	
	Rm. 2 fountain	0.0017	07/29/2016	
	Rm. 3 fountain	0.0052	07/29/2016	
	Rm. 4 faucet	0.0062	07/29/2016	
	Rm. 5 fountain	0.0014	07/29/2016	
	Rm. 6 fountain	0.0058	07/29/2016	
	Library faucet	0.0037	07/29/2016	
	Computer lab fountain	0.0033	07/29/2016	
	Rm. 8 fountain	0.0162	07/29/2016	
	Rm. 9 fountain	0.0011	07/29/2016	
	playground hall fountain	ND	07/29/2016	
	Title 1 faucet	0.0011	12/9/2016	faucet placed out of service, replaced and retested
	Rm. 10 fountain	0.0024	07/29/2016	
	Rm. 11 front faucet	0.003	07/29/2016	
	Rm. 12 fountain	0.0016	07/29/2016	
	Rm. 13 fountain	0.0056	07/29/2016	
	Gymnasium east fountain	ND	07/29/2016	
	Gymnasium west fountain	0.0025	07/29/2016	
	Consession stand faucet	0.001	07/29/2016	
	Modular class-South room	ND	8/24/2016	

	Modular class-North room	ND	8/24/2016		
Santiam Jr./Sr. High	Office area faucet	ND	3/25/2016		
	Red hall fountain	0.001	07/28/2016		
	Black hall fountain	0.0064	07/28/2016		
	Gray hall fountain	0.0045	07/28/2016		
	Special education faucet east	0.0027	07/28/2016		
	Special education faucet west	0.0092	07/28/2016		
	Gymnasium west fountain	0.0113	07/28/2016		
	Gymnasium east fountain	0.0077	07/28/2016		
	Boys locker room faucet	0.0077	07/28/2016		
	Girls locker room faucet	ND	07/28/2016		
	Consession stand faucet	0.0153	07/28/2016		
	Shop building fountain	0.0053	07/28/2016		
	Staff Faucet	0.0012	07/28/2016		
Cafeteria	Cafeteria fountain	0.0056	07/28/2016		
	Kitchen main sink	0.0168	3/25/2016		
	Kitchen back sink	0.0124	07/28/2016		